




ID 1 ~ ID 18 motor

AX-12+ x18



CM-510



BATTERY



CABLE-BAT




DMS



IR RECEIVER



IR SENSOR x2



GYRO SENSOR



BU x20



WA x20



SP1 x4



SP2 x4




F1 x10




F2 x10



F3 x20



F4 x6




F5 x6



F6 x12




F7 x6




F8 x3




F9 x5



F10 x20



F11 x2




F12 x2




F13 x4



F14 x4



F51



F52



F53 x4



F54 x4



F55 x20



F56




F57



F58



F59



F60



RC-100



USB2DXL



SERIAL CABLE



CHARGER

S1 x400

S2 x20

S3 x20

S4 x20

S5 x20

S6 x20

S7 x20

S8 x20

S-B x30

S11 x40


S12 x10

S13 x5

S14 x5

N1 x400

N2 x10



PIN HOLE x14


PIN x14

PLATE 3x7

SINGLE BRACKET x2

CABLE-DMS x3

DRIVER



x6

CABLE-10 x5

x5

CABLE-14 x6

x6

CABLE-18 x4

x4

CABLE-20 x5

x5



SMPS



CD



Quick Start



5P-5P CABLE

PIE-HROBOT.COM